

Product Retirement Notice

PRN # 15 - 03

March 16, 2015

Honeywell Announces Immediate End of Life of 8650 - 2D Bluetooth Ring Scanner

This notice serves as formal communication of Honeywell Scanning & Mobility's intent to immediately discontinue the following product(s):

- 8650 – 2D Bluetooth Ring Scanner

This retirement notice attempts to identify all SKUs affected by the discontinuation of the 8650 – 2D Bluetooth Ring Scanner. It is possible that some part numbers were missed in the list provided. Honeywell reserves the right to include omitted SKUs if they are related to the products listed above, even if the SKU is not specifically listed in this notice. Those omitted SKUs are subject to the terms specified within this document. If you are unsure of a specific SKU, please contact your Honeywell representative for clarification.

Product Name	Part Number	Description
8650	8652100RINGSCR	Bluetooth module with 2D ring imager (SE4400), battery, and two hand/wrist straps (large and small)
8650	8654100RINGSCR	Bluetooth module with 2D ring imager (SE4400), battery, two hand/wrist straps (large and small), and Windows XP wedge
8650	8652103RINGSCR	1D/2D IMAGER RING SCANNER FOR BLUETOOTH MODULE, 2D area imager

Regions Affected:

- | | |
|--|--|
| <input checked="" type="checkbox"/> Asia Pacific (AP) | <input checked="" type="checkbox"/> Europe, Middle East, Africa (EMEA) |
| <input checked="" type="checkbox"/> Latin America (LA) | <input checked="" type="checkbox"/> North America (NA) |

Reason for Retirement:

8650 2D Bluetooth Ring Scanner is being immediately retired due to end of life of crucial components used in the product. Honeywell is in the process of finalizing the replacement product and this will be communicated shortly.

Timeline of Events:

Last Time Buy	Honeywell will not accept hardware or service contract orders after this date	NA
Last Time Ship	Honeywell will not ship product after this date	NA
Stock Rotation Request	Honeywell will not accept requests for stock rotation after this date	NA
Stock Rotation Return	Honeywell must receive all final stock rotated units by this date	NA
End of Service	Honeywell will not offer spare parts or servicing of units after this date	31-Mar-20

Product Retirement Notice

Service and Warranty:

Honeywell will maintain our commitment to our customers by supporting and servicing discontinued product at all worldwide service centers throughout the life of all warranties in place, as long as the required parts are commercially available.

Contact:

Honeywell Scanning & Mobility is committed to providing you with a superior level of customer service. Please contact your Honeywell representative for additional information regarding this communication.

For more information:

www.honeywellaidc.com

Honeywell Scanning & Mobility

9680 Old Bailes Road

Fort Mill, SC 29707

800.582.4263

www.honeywell.com

The Honeywell logo is displayed in a bold, red, sans-serif font.